

Appendix 3 - Photos



Plate 1 General view along crest of dam, from east end looking northwest, showing trees on dam slopes and in reservoir, which is on left-hand side.



Plate 2 Example of damage to the dam from protected species, near to one of the culverts.

Appendix 3 - Photos



Plate 3 Headwall of one of the culverts shown sunken with broken headwall.



Plate 4 Headwall of second culvert shown broken, Condition of brickwork inside culvert also very poor.