

### Appendix 3 Photographs taken January 2015



Figure 2: Relocate double concrete litter bin from crest of Parliament Hill and fix wooden cladding to soften appearance  
(Note 1 Landscape Management Principles)



Figure 3: Move interpretation sign so it does not coincide with the crossing of the two main path routes  
(Note 2 Landscape Management Principles)



Figure 4: Grass Renovation Works, including deep compaction, levelling and post sward establishment