Seddon House Final Roof Apportionment				
			Qualifying Long	Total
Bill Item Page No	Comments	Corporation Cost	Leaseholder	
Works Items				
Apportioned on Structural/ non structural defect basis				
Section 3				
TEMPORARY ACCESS, SCAFFOLD &	included below			
PROTECTION WORKS BALCONY WALKWAYS				
P4 ITEM A-D	Remove existing roof coverings, flashings and clear away	11,414.00	0.00	11,414.00
P4 ITEM E	Break out rainwater outlets and prepare and fit hopper	3,600.00	0.00	3,600.00
P4-5 ITEM F-G	Clean off walls, m g and prepare to receive epoxy mortar Prepare and lay new screed	12,600.00	0.00	12,600.00
	Prepare and fit new doors & frames, prepare			,
P5 ITEM A-C	them for new felt/trim Prepare surface, apply vapour barrier,	6,900.00	0.00	6,900.00
P6 ITEM B-D	insulation boards, edging, underlay	15,800.00	0.00	15,800.00
P6 ITEM D(contd)	Apply new waterproof surface finish	0.00	1,200.00	1,200.00
P7 ITEM A	Dress felts to penetrations, upstands and around rainwater outlets to receive waterproof finish	9,350.00	0.00	9,350.00
	Use roof sheeting on details with underlay,			
P7 ITEM A(contd) P7 ITEM B	extending at least 150mm. lay new roof slabs	1,650.00 16,600.00	0.00	1,650.00 16,600.00
P8 ITEMS A-D	Install aluminium Neaco 'Neatdek' grilles. Fit upstands and trims with sealant as appropriate to door /window thresholds, abutments		0.00	6,300.00
P8 ITEM E - P9 ITEMS A-B	Remove & resite privacy screens/planters & clean exposed areas	3,600.00	0.00	3,600.00
MAIN ROOFS	remove existing roof coverings, flashings and			
P10 ITEMS A-B	clear away	4,900.00	0.00	4,900.00
P10 ITEMS D-E	Prepare chases, recesses etc for coverings and window cills for new felt/trim	400.00	0.00	400.00
P10 ITEMS F-G	Remove old and supply/fit new plant room doors	4,000.00	0.00	4,000.00
P11 ITEMS A-C	Break out plant room rainwater pipes and fit new outlets, pipes & hoppers	2,800.00	0.00	2,800.00
P12 ITEMS A-C	Prepare surfaces, apply vapour barrier, insulation boards, edging, underlay	26,730.00	0.00	26,730.00
P12 ITEM C(contd)	Apply new waterproof surface finish	6,270.00	0.00	6,270.00
	Dress felts to penetrations, upstands and around rainwater outlets to receive waterproof			
P12 ITEM D	finish	200.00	0.00	200.00
P12 ITEM D(contd)	Prepare existing rainwater outlets to receive Refurbidrain and apply waterproofing	0.00	600.00	600.00
P13 ITEMS A-D - P14 ITEM A	Fit lead flashing beneath door thresholds, aluminium trims bedded in sealant to window cills & plant room wall abutments	4,100.00	0.00	4,100.00
BARREL VAULT ROOFS & PARAPET COVERINGS				
	Remove existing membranes, felts, insulation. Apply primer to parapet walls/exposed surfaces. Cut back discharge outlets from	5 000 00	0.00	F 000 00
P15 ITEMS A-D	gutters between barrels Fit trims to parapet walls, prepare barrel	5,920.00	0.00	5,920.00
P15 ITEMS E-G	vault/plant room abutment an apply epoxy mortar	3,600.00	0.00	3,600.00
	Modify design of existing rainwater installation, extend gutter to roof edge, remove existing			
P16 ITEMS A-D	outlets and cap off & make good concrete	3,300.00	0.00	3,300.00
P16 ITEMS E-G	Supply & fix insulation to central gutters and curved surfaces of all barrel vault roofs	4,900.00	0.00	4,900.00

	Fit fillet at junction barrel roof/plant room, apply			
	Triflex liquid membrane, dress to window cills,			
P17 ITEMS A-C	plant room abutments, central gutters	1,369.40	15,330.60	16,700.00
	Fit trims to windows, bed in with sealant, trim bar to barrel roof/plant room abutment and			
P17 ITEMS D-G	apply sealant	2,400.00	0.00	2,400.00
	Clear expansion joint of old material and apply			
P18 ITEM A	new tape between layers of membrane. Replace all sealant	0.00	2,600.00	2,600.00
PLANT ROOM ROOFS		0.00	2,000.00	2,000.00
P19 ITEM A	Remove existing coverings	1,600.00	0.00	1,600.00
		,		,
	Break out/clear chases, recesses, prepare ply on perimeter kerbs to secure edge trim on	1.400.00	0.00	4 400 00
P19 ITEMS B & D-E	Prepare surfaces, apply primer, lay underlay,	1,400.00	0.00	1,400.00
	dress felts to penetrations, upstands and			
P19 ITEMS G-H P20 ITEMS A-C1 -D	around outlets	6,100.00	0.00	6,100.00
	Laurantema et Calaba estas da almas da Cilada	0.00	0.500.00	0.500.00
P20 ITEM C2	Lay waterproof finish, extend edges to fillets Supply and fit trims to kerb edges and ply	0.00	3,500.00	3,500.00
P21 ITEMS A-B	lining	780.00	0.00	780.00
JOINERY REPAIRS				
	Demous design band, act aside as and			
	Remove glazing bead, set aside sound lengths for reuse, Prepare cill for new bead,			
	Fit new glazing bead bedded on sealant,			
P22-23 ITEMS A-E	Individual joinery repairs as directed on site	0.00	8,800.00	8,800.00
	Remove existing sealant to door frames,	0.00	4 700 00	1 700 00
P24 ITEM B-C LIGHTNING PROTECTION	prime surfaces and replace	0.00	4,700.00	4,700.00
LIGHTNING PROTECTION	Design, supply & install lightning protection	0.00	0.00	
P26 ITEMS A-F	system to BS standards plus associated works	0.00	6,600.00	6,600.00
ADDITIONS				
CI 3.2	Identify screed condition adjacent each balcony level property	250.00		250.00
513.2	Clean balcony outlets in preperation for new	200.00		200.00
CI 3.4	felt coverings	1,200.00		1,200.00
CI 4.1	Balcony coverings to be "mopped on" in lieu of "torched on" in view of fire risk	7,249.41	550.59	7.800.00
014.1		7,243.41	550.55	7,000.00
CI 5.2	Infill chase to roof perimeter and make good	1,830.00		1,830.00
	Clean main roof rainwater outlets in	450.00		450.00
CI 6.1	preparation for new felt coverings Install 2. No, lead rainwater chutes between	450.00		450.00
CI 6.3	roof levels at North end	450.00		450.00
	Roofing membrane to barrel vault roofs and			
0171	parapets to be Decothame Gamma 20 system.		8.400.00	8,400.00
CI 7.1	Rake out chase to front edge of barrel vaults		8,400.00	8,400.00
CI 7.2	and make good	1,242.00		1,242.00
	Adapt existing plant room rainwater pipes	4 070 00		1 070 00
CI 8.2	serving barrel vaults	1,670.00		1,670.00
	Sealant fillet to abutment between eyebrown			
CI 8.4	window and Decothane coverings		470.00	470.00
	3 No. Lead collars to valley gutter outlets	240.00		240.00
CI 9.1	discharging onto main roof levels Infill chases to roof perimeters and make good	240.00		240.00
CI 9.3	defective cement/sand	600.00		600.00
	Felt pads beneath lead chute and rainwater			
CI 10.3	pipe on Main roof level Modification of balcony level window cill &	652.00		652.00
	specified metal trims to base of barrel vault			
CI 11.2	balcony window to SW corner	3,800.00		3,800.00
CI 11.4	Window Bead removal works	822.00		822.00
CI 11.5	Fire safety signage to privacy screens		220.00	220.00
CI 11.6	Renewal of seals to balcony level windows		486.00	486.00
	Renew defective glazing to balcony dividing screens (4 No) including making good			
CI 12.1	previously painted services.		2,094.00	2,094.00
Omissions				
CI 3.1	Remove existing roof coverings, flashings and clear away	-3,000.00		-3,000.00
	oloai away	-3,000.00		-0,000.00

Staff Costs Allowance for historic costs (£64775.6) 64,775.60 GRAND TOTAL		51,217.29 381,590.62	-51,217.29 67,565.63	449,156.25
Allowance for historic costs (£64775.6)		51,217.29	-51,217.29	
		51.217.29	-51,217.29	
Staff Costs		I		
		19,665.45	7,051.16	26,716.61
Fixed consultant fees		13,249.36	4,750.64	18,000.00
(Works Outside Main Contract)		0.00	594.31	594.31
Open Spaces - Care of Residents' plants				
Works outside main contract- install electrical meter for contractors services		749.33	0.00	749.33
		1,001.00	2,02 1100	-,002.00
FINAL ACCOUN I Less Liquidated Damages		<u>303,740.19</u> -7,031.00	108,907.81 -2,521.00	412,648.00
completion works FINAL ACCOUNT		1,472.15	527.85	2,000.00
temporary enabling works		84,170.26	30,179.74	114,350.00
Contingencies / Provisional Items		1,232.93	442.07	1,675.00
Preliminaries		42,526.04	15,247.96	57,774.00
Percentage		73.61%	26.39%	
Total Roof Works and Normal Maintenance	Items	174,338.81	62,510.19	236,849.00
Percentage		0.00%	100.00%	
Total Normal Maintenance Items		0.00	16,359.00	16,359.00
				·
Cl 10.2	Timber repairs to door & window frames		4,759.00	4,759.00
ADDITIONS				
P25 ITEM A-G	metalwork, painted concrete, interior roof level lobbies as specified	0.00	11,600.00	11,600.00
	Prepare & decorate all exterior woodwork,			
DECORATIONS				
NORMAL MAINTENANCE ITEMS ALSO BEIN	NG ADDRESSED UNDER THIS CONTRACT			
Percentage		79.07%	20.93%	
TOTAL ROOF WORK ITEMS		174,338.81	46,151.19	220,490.00
CI 11.1	gutters between barrels	-900.00		-900.00
	Apply primer to parapet walls/exposed surfaces. Cut back discharge outlets from			
	Remove existing membranes, felts, insulation.			
CI 10.1	Individual joinery repairs as directed on site.		-8,800.00	-8,800.00
	lengths for reuse, Prepare cill for new bead, Fit new glazing bead bedded on sealant,			
	Remove glazing bead, set aside sound			
CI 8.3	apply sealant		-600.00	-600.00
	bar to barrel roof/plant room abutment and			
CI 8.1	outlets and cap off & make good concrete Fit trims to windows, bed in with sealant, trim	-3,300.00		-3,300.00
	extend gutter to roof edge, remove existing			
	Modify design of existing rainwater installation,			
CI 6.2	new outlets, pipes & hoppers	-200.00		-200.00
CI 6.1	new outlets, pipes & hoppers Break out plant room rainwater pipes and fit	-1,600.00		-1,600.00
CI 5.1	and window cills for new felt/trim Break out plant room rainwater pipes and fit	-1,500.00		-1,500.00
	Prepare chases, recesses etc for coverings	4 500 00		1 500 00
CI 4.1	Prepare chases, recesses etc for coverings and window cills for new felt/trim	-600.00		-600.00
CI 3.3	hopper	-3,600.00		-3,600.00
ICI 3 3	Break out rainwater outlets and prepare and fit hopper	-3 600 00		-3 600 0