

## PLANNING AND TRANSPORTATION COMMITTEE REPORT

### Points to Note:

- There are 14 Public Lifts/Escalators in the City of London estate. This is a report by exception, and hence, only the five listed lifts/escalators that suffered breakdown within the reporting period are shown within this report.
- The report was created on 31 May 2016 and subsequently since this time the public lifts or escalators could have been brought back into service or experienced further breakdowns which will be conveyed in the next report.

Location And Age	Status as of  11/05/2016	% of time in service between 11/05/2016 And 31/05/2016	Number of times reported between 11/05/2016 And 31/05/2016	Period of time Not in Use between 11/05/2016 And 31/05/2016	Comments  Where the service is less than 100%
<b>Atlantic House 2001 SC6458966</b>	IN SERVICE	99.8%	1	1 hr.	<b>19/05/2016</b> – Engineer attended site and found bottom floor landing doors not shutting every time. Cleared track of debris and checked rollers door were not rubbing. Tested & left in service.
<b>Tower Place – Scenic Lift SC6458963</b>	OUT OF SERVICE	60%	1	288 hrs.	<b>20/05/2016</b> - Engineer attended site and found the car doors not shutting at lower ground due to a loose car door roller. Tried to rectify but they were still remaining 6 inches open when closed. Upon further investigation the engineer found a problem motor room incoming supply isolator. Parts required so left lift out of service.
<b>Wood Street Public Lift (Royex House) 2008 SC6458970</b>	OUT OF SERVICE	98.1%	1	9 hrs.	<b>31/05/2016</b> - Engineer attended site and found the lift stopped at top floor with doors not closing fully. Adjusted door zone locking cam and reset but still found the doors going into fault mode. Specialist technician required and hadn't attended when report issued.

## PLANNING AND TRANSPORTATION COMMITTEE REPORT

Location And Age	Status as of  11/05/2016	% of time in service between 11/05/2016 And 31/05/2016	Number of times reported between 11/05/2016 And 31/05/2016	Period of time Not in Use between 11/05/2016 And 31/05/2016	Comments  Where the service is less than 100%
<b>Speed House SC6459146</b>	IN SERVICE	86%	1	67hrs.	<b>16/05/2016</b> - Engineer attended site and found lift out of service at ground floor level with doors opening and closing. Unable to clear the fault as it requires a technical support code. Return Visit on the 19/05/2016 when the specialist engineers identified a fault with the logger. This was repaired and the lift left in service.
<b>Tower Bridge SC6459244</b>	IN SERVICE	98.5%	1	7 hrs.	<b>29/05/2016</b> - Engineer attended site and found doors not closing fully at bottom level. Cleaned out car & landing cills, tested and left in service.

*Additional information*