


PLANNING AND TRANSPORTATION COMMITTEE REPORT 09/02/2021 – 19/02/2021



Code	Name	Time OOS	Availability
0916	Glass South Tower SC6459244	0 00:00	100%
0924	Duchess Walk Public Lift CL24	0 00:00	100%
0944	London Wall Down Escalator SC6458958	0 00:00	100%
0976	Pilgrim Street SC6458969	0 00:00	100%
0978	Atlantic House SC6458966	0 00:00	100%
7345	Speed House Public Lift SC6459146	0 00:00	100%
7921	Little Britain SC6458967	0 00:00	100%
7960	London Wall West SC6458965	0 00:00	100%
7963	London Wall East SC6458964	0 00:00	100%
7964	Blackfriars Bridge SC6462771	0 00:00	100%
7997	33 King Williams Street SC6462850	0 00:00	100%
7998	Tower Place Public Lift SC6458962	0 00:00	100%
7999	Tower Place Scenic Lift SC6458963	0 00:00	100%
7740	Moor House SC6458968	0 01:32	99.42%
7730	Wood Street Public Lift SC6458970	1 02:58	89.78%
0945	London Wall Up Escalator SC6458959	3 12:01	68.17%
0929	Millennium Bridge Inclinator SC6459245	10 23:59	0.00%

Points to Note:

- There are 17 Public Lifts/Escalators in the City of London estate. The report below contains details of the 3 - public escalator/lifts that were out of service for less than 95% of the time.
- The report was created on 19th February 2021 and subsequently since this time the public lifts or escalators may have experienced further breakdowns which will be conveyed in the next report.

PLANNING AND TRANSPORTATION COMMITTEE REPORT 09/02/2021 – 19/02/2021

Location	Status as of 19/02/2021	% of time in service Between 09/02/2021 and 19/02/2021	Number of times reported Between 09/02/2021 and 19/02/2021	Period Not in Use Between 09/02/2021 and 19/02/2021	Comments Where the service is less than 95%
London Wall Escalator (UP) SC6458959	In service	68.17%	1	84 hours	Engineer was unable to reset after a fault reported. Specialist technician returned to site and restored escalator to service on the 16 th February 2021.
Wood Street Public Lift SC6458970	In Service	89.78%	1	27 hours	Lift taken out of service for a safety investigation to be undertaken, lift returned to service when completed as no faults found.
Millennium Bridge Inclinor SC6459245	Out of service	0.00%	1	264 hours	Engineer attended and found a fault with the control panel caused by vandalism, parts required and currently out of service whilst these are received and fitted. The adverse weather conditions have delayed the repair by one week with an expected return to service now scheduled for commencing the 22 nd February 2021.