


PLANNING AND TRANSPORTATION COMMITTEE REPORT 12/06/2021 – 02/07/2021



| Code | Name | Time OOS | Availability |
|------|--|----------|--------------|
| 0924 | Duchess Walk Public Lift CL24 | 0 00:00 | 100% |
| 0976 | Pilgrim Street SC6458969 | 0 00:00 | 100% |
| 0978 | Atlantic House SC6458966 | 0 00:00 | 100% |
| 7730 | Wood Street Public Lift SC6458970 | 0 00:00 | 100% |
| 7921 | Little Britain SC6458967 | 0 00:00 | 100% |
| 7960 | London Wall West SC6458965 | 0 00:00 | 100% |
| 7963 | London Wall East SC6458964 | 0 00:00 | 100% |
| 7964 | Blackfriars Bridge SC6462771 | 0 00:00 | 100% |
| 7997 | 33 King Williams Street SC6462850 | 0 00:00 | 100% |
| 7998 | Tower Place Public Lift SC6458962 | 0 00:00 | 100% |
| 7999 | Tower Place Scenic Lift SC6458963 | 0 00:00 | 100% |
| 0929 | Millennium Bridge Inclinator SC6459245 | 1 05:28 | 94.15% |
| 0916 | Glass South Tower SC6459244 | 1 13:22 | 92.59% |
| 0945 | London Wall Up Escalator SC6458959 | 2 20:06 | 86.49% |
| 0944 | London Wall Down Escalator SC6458958 | 4 16:24 | 77.70% |
| 7740 | Moor House SC6458968 | 5 17:18 | 72.76% |
| 7345 | Speed House Public Lift SC6459146 | 11 09:08 | 45.81% |

Points to Note:

- There are 17 Public Lifts/Escalators in the City of London estate. The report below contains details of the 6 public escalators/lifts that were out of service less than 95% of the time.
- The report was created on 06 July 2021 and subsequently since this time the public lifts or escalators may have experienced further breakdowns which will be conveyed in the next report.

PLANNING AND TRANSPORTATION COMMITTEE REPORT 12/06/2021 – 02/07/2021

| Location | Status as of 02/07/2021 | % of time in service Between 12/06/2021 and 02/07/2021 | Number of times reported Between 12/06/2021 and 02/07/2021 | Period Not in Use Between 12/06/2021 and 02/07/2021 | Comments Where the service is less than 95% |
|---|--------------------------------|---|---|--|---|
| London Wall Down Escalator SC6458958 | In service | 77.70% | 1 | 108 hours | Unfortunately, the service was suspended by members of the public pushing the emergency stop button. We continue to work with our supplier to develop better controls to stop this from happening whilst keeping the health and safety measures in place. |
| Moor House | In Service | 72.76% | 1 | 131 hours | Engineer attended site and found a fault with the lift controller failure, new parts required. Engineer attended site when received and returned the lift to service. |
| Glass South Tower - SC6459244 | In Service | 92.59% | 1 | 36 hours | Engineer attended site and found a fault with the door locking mechanism, new parts required. Engineer attended site when received and returned the lift to service. |
| Millennium Bridge Inclinators SC6459245 | In Service | 94.15% | 1 | 28 hours | Engineer attended site and found a fault with the door locking mechanism, new parts required. Engineer attended site when received and returned the lift to service. |
| London Wall Up Escalator SC6458959 | In Service | 86.49% | 1 | 65 hours | Unfortunately, the service was suspended by members of the public pushing the emergency stop button. We continue to work with our supplier to develop better controls to stop this from happening whilst keeping the health and safety measures in place. |

PLANNING AND TRANSPORTATION COMMITTEE REPORT 12/06/2021 – 02/07/2021

| | | | | | |
|--------------------------------------|------------|--------|---|-----------|--|
| Speed House Public Lift SC6459146 | In Service | 45.81% | 1 | 260 hours | Engineer attended site and found a fault with one of the three power phases to the lift, UKPN attendance required to rectify the problem. UKPN attended on 21 st June 2021, rectified the fault and the lift was left in service. |
|--------------------------------------|------------|--------|---|-----------|--|