DCCS Corporate and departmental risks - detailed report EXCLUDING COMPLETED ACTIONS



Rows are sorted by Risk Score

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating & Score	Risk Update and date of update	Target Risk Rating & Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 003 Lone Working 14-Jan-2016 Liane Coopey; Paul Murtagh	Cause: Not implementing appropriate risk assessment and lone working device to mitigate the risk, not providing training nor effective management supervision to support lone workers. Event: Fail to enforce corporate policy and guidance followed by legislation. Lone working staff not taking adequate control measures if an event was to occur. Effect: Physical or mental harmed to staff can result to investigation and legal action, damaging the reputation of the City of London.	Impact 12	Audit of users has been undertaken and front line teams have been supplied with new devices for staff on request. Monitoring is continuing on a monthly basis Reports are being sent to team managers to encourage them to take ownership of device usage. 24 Nov 2021	Impact	Reduce	Constant

Action no	Action description		Latest Note Date	Due Date
DCCS HS 003c	Tool (PSVT);	Details now being entered for out of city estates onto Orchard and PSVT for the City Estates, as it is City services like Noise, etc., that would be going out to properties (& they don't have access to Orchard). PSVT list reviewed in March 2020 and several households were removed and a few added		31-Mar- 2022

		Next action will be to integrate the PSVT information into the new housing management system. Go live date has been delayed to the 4th quarter 21/22		
DCCS HS 003d	, , , , ,	anticipated increase with the gradual return to site visits has not been seen. Reports of non		31-Dec- 2021

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating & Score	Risk Update and date of update	Target Risk Rating &	Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 002 Failure to carry out and review effective Fire Risk Assessments for more than 5000 units of residential accommodatio n and a number of commercial units 14-Jan-2016 Liane Coopey; Paul Murtagh	Cause Fire Risk Assessments for managed properties not carried out effectively Event Fires do occur from time to time. Effective Assessments reduce the risk and identify if any changes to procedures or maintenance regimes that need to be reviewed or introduced Effect Fires can lead to significant property damage and potential loss of life	Likelihood land land land land land land land lan	A new programme of Fire Risk Assessments is currently being undertaken by Turner Townsend. All high rise assessments should be completed by end 2021. A fire risk assessment action plan for all Barbican and housing estates is in place and is being regularly monitored. by new Fire Task Group. Works have been identified and are being carried out over a period of 18 months to 2 years. Works include the retrofitting of sprinkler systems in 5 high rise blocks, works to improve compartmentalisation and the replacement of entrance doors to meet current fire safety standards. 28 Sep 2021	Likelihood	4	31-Mar- 2022	Constant
Action no	Action description	Latest Note			Action owner	Latest Note Date	Due Date
DCCS HS 002c	Community and Children's Services Committee has approved the retrofitting of sprinklers in the 5 high rise tower blocks within the City's social housing portfolio.	Petticoat Tower and then Great	me with the works commencing at Avon Arthur House is in the process of contacting residents	•	Paul Murtagh	25-Nov- 2021	31-Mar- 2022

		survey properties and complete pre-condition assessments ahead of the works starting in January 2022. • Petticoat Tower will commence in April 2022 and Great Arthur House July 2022. United Living will have two teams delivering the works as Avondale will take approximately 1 year to complete as there are 3 blocks. • A void flat on all three estates has been identified. We are carrying out installations to then be able to show existing residents and members what the sprinklers will actually look like ahead of the proper installations. • The Listed Building Consent application for Great Arthur House has been delayed due to negotiations with planning and difficulty getting a slot in the Planning & Transportation Committee agenda. It is due to go to P&T committee in February 2022			
DCCS HS 002d	Community and Children's Services Committee has approved a programme to replace all main entrance doors in the City's social housing blocks of flats. The new fire doors will provide a minimum of 30 minutes and up to 60 minutes of fire resistance.	5 1 5 5	Paul Murtagh	25-Nov- 2021	31-Mar- 2022

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating	& Score	Risk Update and date of update	Target Risk Rating & Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 006 Failure to deliver new homes programme	Cause: Funding and planning constraints, market volatility and development cost inflation Event: Failure on commitment to deliver 700 new homes by 2025 Effect: Delivery of a reduced number of new homes resulting in diminished HRA income and reputational damage	Likelihood	8	Priority is being given to progress the new developments for COLPAI, Sydenham Hill, Isleden House, Great Arthur House, and York Way Estate. These schemes could deliver 272 new social housing units by 2025. COLPAI is on target to be complete by summer 2022 and will provide 66 new social housing units and 3 commercial units. Sydenham Hill: planning consent was granted by London Borough of Lewisham on 27/08/20 but was	Impact	31-Mar- 2025	

				subject to a Judicial Review which quashed the consent granted. Planning Consent was granted for a second time on 29th June 2021. Tenders have been received and a successful contractor has been identified to take the scheme forward. Isleden House & Great Arthur House developments are on site with Isleden due for completion by March 2022 and Great Arthur House residential conversions by September 2021.				
07-Jan-2020				18 Oct 2021			Reduce	Constant
Paul Murtagh		-						
Action no	Action description	Latest Note				Action owner	Latest Note Date	Due Date
DCCS HS 006a		Nothing further since 2022	e the annual	review report in March – next annual rev	view will be March	Paul Murtagh	28-Sep- 2021	31-Mar- 2022
DCCS HS 006b		Work is still in progr This will be captured Our application to th strategy		Paul Murtagh	29-Sep- 2021	31-Mar- 2022		
DCCS HS 006c	Establish costs and delivery dates for what can be delivered within existing funding streams	Overview Report subnext year	omitted to DO	CCS Committee in March. Next report	will probably be early	Paul Murtagh	28-Sep- 2021	31-Mar- 2022

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating & Score	Risk Update and date of update	Target Risk Rating &	Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 001 Health and Safety procedures 13-Nov-2014 Paul Murtagh	Cause: Failure to meet Health and Safety regulations and City of London procedures within the department and on the properties and estates managed by the Housing Division Event: Accident or fire in property or estates managed DCCS leading to harm / injury to staff member, resident or visitor Effect: Injury to person/s on property or estates managed by DCCS, possible adverse media coverage, external investigation into incident and potential claims for compensation.		Estate standard project completed - pandemic has forced the new structure put in place regarding management responsibility. Restructure part of TOM process. Anticipated to be complete by December 2021 28 Sep 2021	Impact	4	31-Mar- 2022 Reduce	Constant
Action no	Action description	Latest Note				Latest Note Date	Due Date
DCCS HS 001h	Failure to recruit new health & safety advisor - either on a temporary or permanent basis.	Temporary post holder in place. Currently recruitment moratorium	emporary post holder in place. Will complete once permanent post holder appointed. urrently recruitment moratorium				31-Dec- 2021

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating	& Score	Risk Update and date of update	Target Risk Rating &	Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 004 Housing Finance Changes	Cause Changes to housing financing Event Possible shortfall in Housing Revenue Account funding Effect – Inability to fund the estimated 30 year expenditure plans regarding the City of London's Social Housing	Likelihood	6	A review and remodel the Housing Revenue Account 30 year Business Plan is being undertaken. This is a complex task looking at assets and finances across this period.	Likelihood	4	31-Mar- 2022	•
15-Aug-2016 Paul Murtagh				24 Nov 2021			Reduce	Constant

Action no	Action description			Latest Note Date	Due Date
DCCS HS 004d	A further review and remodelling of the 30 year Business Plan is to be undertaken.	8 s y	Murtagh		31-Dec- 2021

Risk no, title, creation date, owner	Risk Description (Cause, Event, Impact)	Current Risk Rating & Scot	Risk Update and date of update	e Target Risk Rating & Score	Target Date/Risk Approach	Current Risk score change indicator
DCCS HS 005 Major works programme 07-Jan-2020 Paul Murtagh	Cause: Shortfall in funding/increase in costs of major works programme Event: Inability of the City of London to fund major works improvements and fire safety works Effect: Detrimental to property conditions and living standards	Impact	Review of Major Works Progr completed and awaiting Comm approval (date to be confirmed Delivery of Major Works are r anticipated before 2022 18 Oct 2021	nittee Booking and a second se		Constant

Action no	Action description		Latest Note Date	Due Date
	3 1 5 5	· · · · · · · · · · · · · · · · · · ·	1	31-Mar- 2022