



Typical Cross Sections




Existing

KEY


- Office
- Cultural
- Cultural Restaurant / Café
- Restaurant / Café
- Cycle Store
- Shower / Changing Room
- Livery Hall

Proposed



Existing (left) and Proposed (right) Section North-South - 1



Typical Cross Sections



Existing


Proposed

- KEY
- Office
 - Cultural Office
 - Cultural Restaurant / Café
 - Restaurant / Café
 - Cycle Store / Café
 - Shower / Changing Room
 - Livery Hall / Shower / Changing Room



Existing (left) and Proposed (right) Section North-South - 2

Site Elevations




Existing

Proposed


Existing (left) and Proposed (right) Site South Elevation

Site Elevations



Existing (left) and Proposed (right) Site West Elevation

Site Elevations




Existing


Proposed

Existing (left) and Proposed (right) Site North Elevation

Site Elevations



Existing



Proposed

Existing (left) and Proposed (right) Site East Elevation

Extract from TVBHIA
Verified Views



4826_1101

Existing



4826_1105



4826_1106



4826_1151

Existing



4826_1155



4826_1156



4826_1201

Existing



4826_1205



4826_1206



4826_1251

Existing



4826_1255

Proposed



4826_1256



4826_1221

Existing



4826_1225

Proposed



4826_1226



4826_1311

Existing



4826_1315



4826_1316