


Hampstead Heath Consultative Committee - Ponds Project Update - Appendix 1



Picture 1 - Temporary dam at Model Boating Pond with additional piles stabilising the centre.



Picture 2 - De-silting Model Boating Pond using excavators



Picture 3 - Silt deposited to dry out in work compound next to Model Boating Pond.





Picture 4 - Completed works at Viaduct Pond



Picture 5 - Completed works at Vale of Health



Picture 6 - Works underway building the culvert between Hampstead No. 2 and 1.





Picture 7 - Works underway building the culvert between Hampstead No. 2 and 1.



Picture 8 - An oak retaining wall is installed to raise the dam at Stock Pond.



Picture 9 - Work compound and temporary access route at the back gate of Ladies Pond.