

Appendix 1 - Concrete repairs to Cullum Welch House

Schedule of Photographs

North Elevation



Photograph 1: North Elevation, Cullum Welch House. Showing balustrades and external staircase.



Photographs 2a and 2b: North Elevation, Cullum Welch House. Showing damage to vertical bars of balustrade and to a cill after removal of loose concrete. Photographs were taken before the installation of safety netting.

South Elevation



Photograph 3: South Elevation, Cullum Welch House. Concrete elements are painted white.



Photograph 4: South Elevation, Cullum Welch House. View of typical windows planters and pot holders which span two dwellings (partition wall at the centre of the view). Photograph was taken before the installation of safety netting.



Photograph 5: South Elevation, Cullum Welch House. Close up view of planter and pot holder showing spalled concrete and exposed rebar after removal of loose material.