


## Appendix 4 | Current site progress



**Phase 1 Area:** Little Britain footway from Montague Street, resurfacing completed  
- Awaiting installation of street furniture and tree planting/planters



**Phase 1 Area:** Little Britain | Completed resurfacing and example of Culture Mile branded bollards  
- Awaiting installation of additional street furniture in the area

---

## Appendix 4 | Current site progress




Phase 2 Area: Giltspur Street- Hoarding to Pathology Building under development  
- City access currently being programmed



## Appendix 4 | Comparative Images



Phase 1 Area: Little Britain looking north west from Montague Street Circa 2004



Phase 1 Area: Photomontage of proposals for Little Britain looking north west



## Appendix 4 | Comparative Images



Phase 2 Area: Current works underway in West Smithfield/Giltspur Street



Phase 2 Area: Photomontage of proposals for West Smithfield/Giltspur Street