

Appendix 4 | Current site progress



Phase 1 Area: Little Britain footway from Montague Street, resurfacing completed
- Awaiting installation of additional street furniture and tree planting



Phase 1 Area: Little Britain | Completed resurfacing and example of Culture Mile branded bollards
- Awaiting installation of additional street furniture in the area

Appendix 4 | Current site progress




Phase 2 Area: Giltspur Street- Hoarding to Pathology Building under development
- City access currently being programmed

Appendix 4 | Comparative Images



Phase 1 Area: Little Britain looking north west from Montague Street Circa 2004



Phase 1 Area: Photomontage of proposals for Little Britain looking north west

Appendix 4 | Comparative Images



Phase 2 Area: Current works underway in West Smithfield/Giltspur Street (July 2022)



Phase 2 Area: Indicative photomontage of proposals for West Smithfield/Giltspur Street