

Lauderdale Tower

ORDER_ID	PROP_CDE	REQUISITION_ADDR1	REPORT_DATE	CONTRACTOR_CDE	DESC_SHORT
5032954	BE11C2	Lauderdale Tower - Internal	14-Dec-00	Ove Arup & Partners	Inspect concrete wall
5034589	BE11C1	Lauderdale Tower	12-Mar-01	V.J. Driver Building Contractor	DIAMOND BLADE CUTTING THROUGH CONCRETE
5050245	BE11F163	163 Lauderdale Tower	03-Feb-04	Grout Injection Specialists Ltd	REPAIRS TO STRUCTURAL CONCRETE TO BALCONY O/S 163
5057611	BE11F102	102 Lauderdale Tower	09-Jun-05	DOR4	CONCRETE REPAIRS TO PARAPET WALL TO BALCONY
5070406	BE11F373	373 Lauderdale Tower	25-Jul-07	Forest Environmental	REPAIR EXTERNAL CRACK TO CONCRETE UNDER WINDOW ABOVE THE PATIO.
5070916	BE11F373	373 Lauderdale Tower	31-Aug-07	Forest Environmental	REPAIR ADDITIONAL CRACKS IN CONCRETE ABOVE WINDOW ON THE PATIO.
5071577	BE11F143	143 Lauderdale Tower	16-Oct-07	Fairhurst Ward Abbots	Concrete repairs to exterior balcony wall
5083433	BE11F313	313 Lauderdale Tower	02-Dec-09	Fast Clear Drains	Investigation
5083464	BE11C3	Lauderdale Tower - External	03-Dec-09	Forest Environmental	REPAIR CRACK IN CONCRETE FOLLOWING WATER PEN.
5085392	BE11C3	Lauderdale Tower - External	06-Apr-10	Forest Environmental	REPAIR CRACKS TO CONCRETE FOLLOWING WATER PENETRATION
5091564	BE11F373	373 Lauderdale Tower	13-Apr-11	Fast Clear Drains	CARRY OUT CONCRETE INJECTION WORKS TO YELLOW BEDROOM
2038208		Lauderdale Tower - External	20/06/11 13:42	Vertical Technology Ltd	Lauderdale Tower - 3 man Inspection Team Required
2040125		Lauderdale Tower - External	09/08/11 09:11	Fast Clear Drainage	Inspect Loose concrete in Parapet Wall (152

Shakespeare Tower

ORDER_ID	PROP_CDE	REQUISITION_ADDR1	REPORT_DATE	CONTRACTOR_CDE	DESC_SHORT
5035279	BE12F321	321 Shakespeare Tower	19-Apr-01	C.D.N. Property Services Ltd	Concrete repairs to patio/balcony
5043432	BE12F211	211 Shakespeare Tower	08-Oct-02	Tautbuild	Concrete repair
5050732	BE12F211	211 Shakespeare Tower	05-Mar-04	Tautbuild	Renew blown concrete.
5058678	BE12F72	72 Shakespeare Tower	31-Aug-05	Tautbuild	Repair balcony
5075696	BE12F171	171 Shakespeare Tower	12-Jun-08	Fairhurst Ward Abotts	REMOVE PLASTER FROM CEILING FOLLOWING WATER PEN FROM ABOVE
5079373	BE12C3	Shakespeare Tower - External	05-Feb-09	Tautbuild	CONCRETE REPAIRS TO PARAPET WALL ALONG BALCONY O/S 92
5084068	BE12F113	113 Shakespeare Tower	13-Jan-10	Fairhurst Ward Abotts	Balcony
5090297	BE12F101	101 Shakespeare	27-Jan-11	Tautbuild	Concrete Cill Outside Kitchen Window is Loose
2038818		31 Cromwell Tower	04-Jul-11	Fairhurst Ward Abbotts Ltd	Inspect Balcony For Crack In the Concrete

Cromwell Tower

ORDER_ID	PROP_CDE	REQUISITION_ADDR1	REPORT_DATE	CONTRACTOR_CDE	DESC_SHORT
5042934	BE13F223	223 Cromwell Tower	04-Sep-02	Tautbuild	Concrete repair
5043577	BE13F112	112 Cromwell Tower	15-Oct-02	Tautbuild	Renew patio felts & repair concrete
5063181	BE13C2	Cromwell Tower - Internal	09-May-06	Fairhurst Ward Abotts	39th floor - near lift B - make good concrete damage
5063607	BE13C1	Cromwell Tower	02-Jun-06	Fairhurst Ward Abotts	01 car park - concrete repairs
5065398	BE13F372	372 Cromwell Tower	20-Sep-06	By Design Sealants Ltd	Mastic works
5065971	BE13F391	391 Cromwell Tower	17-Oct-06	Forest Environmental	REPAIR CRACK TO CONCRETE FOLLOWING LEAK INTO FLAT
5069193	BE13F303	303 Cromwell Tower	03-May-07	Fairhurst Ward Abotts	Check concrete for damage
5071758	BE13F282	282 Cromwell Tower	26-Oct-07	Fast Clear Drains	repair balcony
5074607	BE13F121	121 Cromwell Tower	09-Apr-08	Fairhurst Ward Abotts	Carryout concrete repair on balcony
5076935	BE13C3	Cromwell Tower - External	08-Sep-08	Forest Environmental	INJECT CRACKS IN CONCRETE AS DIRECTED
5080033	BE13F51	51 Cromwell Tower	27-Mar-09	Fairhurst Ward Abotts	concrete repairs
5087898	BE13C3	Cromwell Tower - External	21-Sep-10	Tautbuild	RENEW BALCONY FELTS O/S 122 FOLLOWING WATER PENETRATION
2044440		81 Cromwell Tower	29/11/11 11:29	Structural Renovations	Carry out Works to Remove Concrete Outside 81 as per email to Chris Bate